



## Fuel tap repair set

repair set for fuel valve FCK-36

**Price: €2.94**

### Basic Data

Supplier Article Number:	81000360
MSRP:	€15.59
SB-Article	No
Brand/Supplier	TOURMAX
Unit of measure:	PIECE

### Technical Data

Design	fuel tap
Range of application	repair set
Variant	Article