



KEYSTER Carburetor repair set

KH-0585NF

The set contains following articles:

2 x float chamber gasket

- Keyster = K-10F

2 x cover gasket

2 x float chamber valve

- Keyster = KVN-16R30

- OEM = 16011-169-004 replaced by 16011-GBF-B41

- OEM = 16011-393-004 replaced by 16011-KCK-910

- OEM = 16011-382-004 replaced by 16011-KG0-891

1 x adjuster screw

1 x jet needle E3050C=#D270

1 x jet needle 3UB=#D337

2 x needle jet

2 x pilot jet

1 x main jet #112

- Keyster = KHM-110112

1 x main jet #110

- Keyster = KHM-110110

1 x throttle stop jet #42

Price: €10.31

Basic Data

Supplier Article Number:

KH-0585NF

MSRP:	€44.90
SB-Article	No
Brand/Supplier	KEYSTER
Unit of measure:	PACKAGE

Technical Data

Design	carburetor parts
Range of application	repair set
Variant	Article