



ROCKSHOX Service Kit

service kit damper for mod. from 2010

Price: 7,61 €

suitable for:ROCKSHOX Totem 2-Step Air Mission Control + Motion Control DH (2007-2010)ROCKSHOX Totem Coil Mission Control (DH) + Motion Control IS (2007-2010)ROCKSHOX Totem Solo Air Mission Control + Motion Control DH (2007-2010)

Datos maestros

Número de artículo del proveedor:	11.4015.431.000
EAN	710845624483
UVP	28,00 €
DST-Code	2005
Fedas-Code	160300
Bidex-Code	201090
SB-Artículo	No
Marca/Proveedor	ROCKSHOX
Unidad de medida:	PIECE
Weight	0.032 kg

Datos técnicos

Artículo	Ersatzteil
----------	------------